

VALKING WORKING SURFACES

PHOTO SOLICE: WWW. OSHA GOV

PA OSHA CONSULTATION

Remember...

Control slip/trip/fall hazards from ground level by:

- Keeping walking/working surfaces as clean and dry as possible
- Making sure your footwear is as slip resistant as possible
- Requiring drainage for wet operations
- Cleaning up or marking and reported spills
- Removing ice and snow frequently and regularly
- Covering or re-routing cords, hose or other protruding items

Control falls from elevation by:

- Engineering out the need to work in elevated position
- Installing guardrails are often used, whether temporary or permanent
- As a last resort, use a Personal Fall Arrest System (PFAS)

Prevent structural collapse by:

- Ensuring walking/working surfaces are structurally sound
- Ensuring surfaces are able to support